


C/C #

03500.015938

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
HIROAKI SAKAI, ET AL.)
Appln. No.: 09/987,297)
Filed: November 14, 2001)
For: IMAGE FORMING APPARATUS AND)
PROCESS CARTRIDGE INCLUDING A)
DEVELOPING DEVICE PROVIDED AT)
LEAST WITH A DEVELOPER HOLDING)
MEMBER FOR HOLDING A DEVELOPER)
CONTAINING A TONE AND A)
DEVELOPER REGULATING MEMBER)

Examiner: S. S. Y. Lee
Group Art Unit: 2852
Patent No.: 6,823,159 B2
Issued: November 23, 2004
February 8, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
FEB 16 2005
of Correction

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.


FEB 17 2005

02/10/2005 H8UTEM1 00000137 6823159 100.00 OP
01 FC:1811

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' attorney, Gary M. Jacobs, may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,



Jack S. Cubert
Attorney for Patentees
Registration No. 24,245

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2200

JSC/llp

DC_MAIN 192367v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,823,159 B2
DATED : November 23, 2004
INVENTOR(S) : HIROAKI SAKAI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE

Item (57), Abstract, "valve" should read --value--.

COLUMN 3

Line 23, "speed" should read --sleeve--.

Line 27, "speed" should read --sleeve--.

COLUMN 4

Line 32, "expression" should read --expression (5)--.

Line 49, "an" should read --a--.

COLUMN 9

Line 32, "thus" should read --thus,--.

COLUMN 11

Line 9, "power" should read --powder--.

Line 12, "mechanism" should read --mechanical--.

Line 46, "crushing-process" should read --crushing process--.

COLUMN 17

Line 19, "HENSHELL" should read --HENSCHEL--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,823,159 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,823,159 B2

DATED : November 23, 2004

INVENTOR(S) : HIROAKI SAKAI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18

Line 5, "SHELL" should read --SCHEL--.

Line 25, "though" should read --through--.

COLUMN 19

Line 42, "HENSHELL" should read --HENSCHEL--.

COLUMN 22

Line 54, "conditions D)" should read --conditions i)--.

Line 56, "D)" should read --i)--.

COLUMN 23

Line 5, "more, wherein" should read --more,
wherein-- (new paragraph).

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,823,159 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) JSC/tp DC_MAIN 192373



FEB 17 2005

03500.015938



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: S. S. Y. Lee
HIROAKI SAKAI, ET AL.)	
	:	Group Art Unit: 2852
Appln. No.: 09/987,297)	
	:	Patent No.: 6,823,159 B2
Filed: November 14, 2001)	
	:	Issued: November 23, 2004
For: IMAGE FORMING APPARATUS AND)	
PROCESS CARTRIDGE INCLUDING A	:	February 8, 2005
DEVELOPING DEVICE PROVIDED AT)	
LEAST WITH A DEVELOPER HOLDING	:	
MEMBER FOR HOLDING A DEVELOPER)	
CONTAINING A TONE AND A	:	
DEVELOPER REGULATING MEMBER)	

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

FEB 17 2005

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' attorney, Gary M. Jacobs, may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,



Jack S. Cubert
Attorney for Patentees
Registration No. 24,245

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2200

JSC/llp

DC_MAIN 192367v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,823,159 B2

DATED : November 23, 2004

INVENTOR(S) : HIROAKI SAKAI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE

Item (57), Abstract, "valve" should read --value--.

COLUMN 3

Line 23, "speed" should read --sleeve--.

Line 27, "speed" should read --sleeve--.

COLUMN 4

Line 32, "expression" should read --expression (5)--.

Line 49, "an" should read --a--.

COLUMN 9

Line 32, "thus" should read --thus,--.

COLUMN 11

Line 9, "power" should read --powder--.

Line 12, "mechanism" should read --mechanical--.

Line 46, "crushing-process" should read --crushing process--.

COLUMN 17

Line 19, "HENSHELL" should read --HENSCHEL--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,823,159 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) JSC/tp DC_MAIN 192373



FEB 17 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,823,159 B2

DATED : November 23, 2004

INVENTOR(S) : HIROAKI SAKAI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18

Line 5, "SHELL" should read --SCHEL--.

Line 25, "though" should read --through--.

COLUMN 19

Line 42, "HENSHELL" should read --HENSCHEL--.

COLUMN 22

Line 54, "conditions I)" should read --conditions i)--.

Line 56, "I)" should read --i)--.

COLUMN 23

Line 5, "more, wherein" should read --more,
wherein-- (new paragraph).

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,823,159 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) JSC/ltp DC_MAIN 192373



FEB 17 2005